Flaps adjusted because it could not be opened smoothly